


MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A

(12) AD

Report 2392

STATUS OF THE DEVELOPMENT OF A LONG-LIFE ENGINE COOLANT SYSTEM

November 1983



Approved for public release; distribution unlimited.

United States Army Belvoir Research & Development Center Fort Belvoir, Virginia 22060 Destroy this report when it is no longer needed. Do not return it to the originator.

《西班牙》《李文学》

The citation in this report of trade names of commercially available products does not constitute official endorsement or approval of the use of such products,

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
2392	AD-A143 598	
4. TITLE (and Subtitio)		5. TYPE OF REPORT & PERIOD COVERED
STATUS OF THE DEVELOPMENT OF A LONG-	LIFE ENGINE	
COOLANT SYSTEM		Interim
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s)		8. CONTRACT OR GRANT NUMBER(a)
James H. Conley and Charles I. Collins		
Julios II. Comey and Charles I. Comin		
		10 DOGGAM ELEMENT BOLLECT TASK
9. PERFORMING ORGANIZATION NAME AND ADDRESS Fuels and Lubricants Division, STRBE-VF; Materia	ils, Fuels, and Lubricants	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
Laboratory; Belvoir Research and Development Cer	nter; Fort Belvoir, VA	1L762733AH20
22060		
11. CONTROLLING OFFICE NAME AND ADDRESS Fuels and Lubricants Division, STRBE-VF; Materia	1. F. d 4 F. b. t	12. REPORT DATE
Laboratory; Belvoir Research and Development Ce		November 1983
22060	inter, Port Belvoir, VA	13. NUMBER OF PAGES
14. MONITORING AGENCY NAME & ADDRESS(If differen	nt from Controlling Office)	15. SECURITY CLASS. (of this report)
		Unclassified
		154. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)		
Approved for public release; distribution unlimited	•	
•		
		ì
17. DISTRIBUTION STATEMENT (of the abetract entered	d in Block 20, if different fro	m Report)
		į
19. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on toverse side, if necessary a	md identify by block number)	
Antifreeze Extender Inhibitor	• • •	· ·
Corrosion Sensor Coolant		j
Filter/Conditioner		
Antifreeze		i
20. ABSTRACT (Concluse on reverse side If resessory a	ad identify by black suphers	
The objective of this study is to evaluate two pro	ototype long-life coolant s	systems in actual vehicle tests. The systems
utilize an electronic coolant condition sensor in con	njunction with either the	newly developed MIL-A-53009 Extender
Additive or a commercial spin-on filter/conditioner	unit.	· · · · · · · · · · · · · · · · · · ·

Both systems were started with an antifreeze with a partially depleted inhibitor system. Results show that, to date, there has been no apparent depletion of the additive systems in either vehicle, and the sensors are functioning properly.

DD 1777 1473

EDITION OF 7 MOV 65 IS OBSIDE HTS

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered

CONTENTS

Section	Title	Page
	ILLUSTRATIONS	iv
	TABLES	v
I	BACKGROUND	1
п	DETAILS OF TEST	2
III	RESULTS OF TEST	2
īV	CONCLUSIONS	2



iii

TABLES

Table	Title	Page
1	1/4-Ton Jeep Test Results	6
2	1 1/4-Ton Truck Test Results	7

ILLUSTRATIONS

Figure	Title	Page
1	Long-Life Coolant System Schematic for 1/4-Ton Jeep	4
2	Long-Life Coolant System Schematic for 1-1/4-Ton Truck	5

STATUS OF THE DEVELOPMENT OF A LONG-LIFE COOLANT SYSTEM

I. BACKGROUND

The advent of the 1973 energy crisis resulted in investigations directed toward reclaiming used antifreeze. One study, described in MERADCOM Report 2166, shows that it is possible to reclaim used antifreeze. A second study, MERADCOM Report 2265, describes an antifreeze extender package that is simply added, in solution, to a used and marginal antifreeze to reinhibit the coolant and prevent corrosion. A new Military Specification covering this material, MIL-A-53009, has been issued. During this same period, industry developed a spin-on-type filter/conditioner based on a solid extender additive package, which was successfully tested in simulated service tests with military antifreeze. Both approaches adequately reinhibit the coolant and prevent corrosion of cooling system metals. However, the filter/conditioner approach requires hardware additions; the additive method specified in MIL-A-53009 does not.

Recent developments in solid state electronics have made it possible to develop a coolant condition sensor, one which will indicate when a coolant's inhibitor system has been depleted to the point where the coolant should be replaced or reinhibited before any significant corrosion of the cooling system metals has taken place. The military standard antifreeze, MIL-A-46153, contains inhibitors that are considered anodic-type inhibitors. Those anions present form passive films on the metal surfaces and thereby retard further corrosion. The measurement technique requires a dual electrode system (sensing and reference) and provides an indirect measurement of coolant corrosivity. As the inhibitors become depleted in the coolant the potential of a steel or an aluminum electrode would shift towards more negative values. In practice the reference is silver and the sensing electrode consists of steel electrically shorted to aluminum to form a galvanic couple for increased sensitivity. The electrometer is capable of measuring the in-situ potential of the sensing electrode versus a reference electrode which in turn activates a warning device, such as a light-emitting diode (LED), when the potential difference exceeds a preset value.

The combination of the new inhibitor additive technology with the electronic coolant condition sensor unit has resulted in the development of two prototype long-life coolant systems. Both systems utilize the electronic sensor in operating vehicles. In one system, the MIL-A-53009 extender package is used for re-inhibition; in the other system, the commercial spin-on filter/conditioner is used for the same purpose.

James H. Conley and Robert G. Jamison, "Reclaiming Used Antifreeze," MERADCOM Report 2166, March 1976.

² James H. Conley and Robert G. Jamison, "Development of an Antifreese Extender and Water Inhibitor for Automotive Cooling Systems," MERADCOM Report 2265, December 1978.

Military Specification, MIL-A-53009, "Additive, Antifreese Extender, Liquid Cooling System," 25 January 1983.

Robert Babolian and Gardnew S. Haynes, "Detecting Coolant Corrosivity with Electrochemical Sensors," Presented at ASTM Committee D-15 Symposium on State of the Art in Engine Coolant Testing, 10 April 1979.

Military Specification, MIL-A-46153, "Antifreese, Ethylene Glycol, Inhibited, Heavy Duty, Single Package," 31 July 1979.

II. DETAILS OF TEST

Approximately 10 gallons of used antifreeze was collected from vehicles in the field. The antifreeze was tested with the MIL-T-36812 Reserve Alkalinity Test Kit⁶ and showed that the antifreeze was "marginal" which indicates low inhibitor level.

Two vehicles were selected as the test vehicles, a 1/4-ton Jeep and a 1-1/4-ton truck. Both vehicles were fitted with an electronic coolant condition sensor with the warning light installed on the dashboard inside the driver's compartment. It was necessary to modify the electrical circuit since the sensor operates on 12-V d.c.; the military vehicles operate on a 24-V d.c. system.

Both vehicles were charged with the used antifreeze and an initial sample was taken for test of pH and reserve alkalinity (RA). MIL-A-53009 additive was added to the 1/4-ton Jeep cooling system at a rate of three volume percent based on the total system volume. The commercial spin-on filter/conditioner unit was installed on the 1-1/4-ton truck in a by-pass mode. Every month thereafter a small sample was removed from each vehicle and the tests were repeated in the laboratory for pH and RA values.

Block diagrams of the two prototype systems are shown in Figures 1 and 2. Each system is set up to indicate when the inhibitor level is low by activation of a red warning light mounted on the vehicle instrument panel.

III. RESULTS OF TESTS

Results of the tests are shown in Tables 1 and 2. The data clearly show that after reinhibition, the pH and reserve alkalinity values are at acceptable levels and have remained so for the entire test period. Slight variations in the values are attributed to the fact that samples have been removed and the volume of coolant readjusted.

Comparison of the mileage and hours of operation shows that the vehicles are at idle a considerable percent of the total operating time. Engine operation under idling conditions is considerably more taxing to the coolant than is continued running.

Both prototype systems are operating properly including the coolant condition sensors. The red warning lights come on when the vehicles are first started and go out immediately and remains out as they should if the inhibitor level is adequate.

Military Specification, MIL-T-36812, "Test Kit, Reserve Alkalinity, Antifreeze," 6 June 1972.

IV. CONCLUSIONS

Since the reserve alkalinity values of both systems have remained fairly high over the test period, it is evident that the test will have to be continued until the inhibitors in both systems have been depleted to that point where the warning lights are activated in order to determine if the total system, sensor, and re-inhibitor, perform adequately.




Figure 1. Lang-life cookent system schematic for 1/4-ton joop.




Figure 2. Long-life coolent system schematic for 1-1/4-ton truck.

Table 1. 1/4-Ton Jeep Test Results

Month	ρĦ	Reserve Alkalinity	Total Miles	Total Hours
l	6.8*	12.7*	()	()
1	8.0	21.4	84.4	7.2
2	8.0	21.3	168.2	19.8
3	8.0	21.6	272.2	44.1
1	8.0	20.2	353.2	59.5
5	8.0	20.5	106.8	61.3
6	7.8	20.5	455.9	66.8
7	8.1	21.0	508.9	77.9
8	8.1	21.7	593.0	87.9
9	8.0	21.2	722.0	93.3
10	8.0	21.6	860.4	151.9
11	8.0	21.7	1028.5	210.8

Initial fill values without extender addition

Table 2. 1 1/4-Ton Truck Test Results

Month	Hq	Reserve Alkalinity	Total Miles	Total Hours
l l	6.8*	12.5*	0	0
1	7.8	20.4	32.0	
2	7.9	20.5	308.4	17.7
3	7.8	20.0	434.4	35.7
1	8.0	20.1	623.4	96.7
5	7.8	20.0	762.4	119.6
6	7.8	20.0	970.2	142.5
7	7.8	20.0	1145.2	160.3
8	7.8	20.0	1346.9	185.1
9 .	8.0	20.3 .	1490.7	197.4
10	8.1	21.9	1500.0	197.9
11	8.0	21.6	1 735.8	216.2
12	8.6	21.4	2619.3	244.8
13	8.0	21.5	2691.3	256.5

Initial fill values before installation of filter/conditioner.

DISTRIBUTION FOR BELVOIR RESEARCH AND DEVELOPMENT (REPORT 2392

No. Copies	Addressee	No. Copies	Addressee
	Department of Defense	1	Director
			Army Materials and Mechanics
ı	Director, Technical Information		Research Center
	Defense Advanced Research		ATTN: DRXMR-PL, Technical
	Projects Agency		Library
	1400 Wilson Blvd		Watertown, MA 02172
	Arlington, VA 22209		
•	•••	l	Technical Library
ı	Director		Chemical Systems Laboratory
	Defense Nuclear Agency		Aberdeen Proving Ground,
	ATTN: TITL		MD 21010
	Washington, DC 20305	ı	C. man in 1 is
12	Defense Technical Information		Commander
'•	Center		US Army Aberdeen Proving Ground
	Cameron Station		ATTN: STEAP-MT-U
	Alexandria, VA 22314		(GE Branch)
			Aberdeen Proving Ground, MD,
•	Department of the Army	•	21005
ı	Commander, HQ TRADOC	1	Director
	ATTN: ATEN-ME		US Army Materiel Systems
	Fort Monroe, VA 23651		Analysis Agency
			ATTN: DRXSY-CM
ı	HQDA (DAMA-AOA-M)		Aberdeen Proving Ground, MD,
	Washington, DC 20310		21005
1	HQDA (DALO-TSM)	1	Director
	Washington, DC 20310		US Army Materiel Systems
			Analysis Agency
1	HQDA (DAEN-RDL)		ATTN: DRXSY-MP
	Washington, DC: 20314		Aberdeen Proving Ground, MD, 21005
1	HQDA (DAEN-MPE-T)		
	Washington, DC 20314	1	Director
-		-	US Army Ballistic Research
i	Commander		Laboratory
	US Army Missile Research &		ATTN: DRDAR-TSD-S (STINFO)
	Development Commund		Aberdeen Proving Ground.
	ATTN: DRSMI-RR		MD 21005

Comment of the second of the second consists of the second of the second

Redstone Arsenal, AL 35809

No. Copies	Addressee	No. Copies	Addressee
i	Director	2	Special Forces Detachment.
	US Army Engineer Waterways		Europe
	Experiment Station		ATTN: PBO
	ATTN: Chief, Library Branch,		APO New York 09050
	Technical Information Center		
	Vicksburg, MS 39180	2	Engineer Representative USA Research & Standardi-
1	Commander		zation Group (Europe)
	US Army Armament Research &		Box 65
	Development Command		FPO 09510
	ATTN: DRDAR-TSS, No. 59		
	Dover, NJ 07801	I	Commander
		•	Rock Island Arsenal
1	Commander		ATTN: SARRI-LPL
	US Army Troop Support &		Rock Island, IL 61201
	Aviation Materiel Readiness		Work Islands 112 Organi
	Command	1	HQDA
	ATTN: DRSTS-MES (1)	•	ODCSLOG
	4300 Goodfellow Blvd		DALO-TSE
	St. Louis, MO 63120		Room 1E588
2	Director		Pentagon, Washington,
_	Petrol & Fld Svc Dept	•	DC 20310
	US Army Quartermaster School		
	Fort Lee, VA 23801	1	Plastics Technical Evalua-
		~	tion Center
1	Commander		ARRADCOM, Bldg 3401
-	US Army Electronics Research &		ATTN: A. M. Anzalone
	Development Command		Dover, NJ 07801
	Technical Library Division		
	ATTN: DELSD-L	1	Commander
	Fort Monmouth, NJ 07703	-	Frankford Arsenal
i	President		ATTN: Library, K2400, B151-2
1	US Army Aviation Test Board		
	ATTN: STEBG-PO		Philadelphia, PA 19137
	Fort Rucker, AL 36360	1	Commandant
	FUIT RUCKET, AL SAMA		
1	US Army Aviation School		US Army Engineer School ATTN: ATZA-CDD
•	Library		Fort Belvoir, VA 22060
	P. O. Box Drawer 0		FOR BEIVOIR, VA 22000
	Fort Rucker, AL 36360	1	President
	tont Huber, Ale anama	L	
2	HO 102 D Infants Datasets		US Army Airborne, Commu- nications & Electronics
ź	HQ, 193 D Infantry Brigade (Pan)		ATTN: STEBF-ABTD
	ATTN: AFZU-FE		
			Fort Bragg, NC 28307
	APO Miami 34004		

THE STATE OF SECOND 1888SSS WINDOWS STATES WINDOWS WINDOWS SECOND SECONDS TO THE SECOND SECONDS

Addressee	No. Copies	Addressee
Commander IIQ, 39th Engineer Battalion (Cbt)	ı	Chief, Combined Arms Support Lab. STRBE-X Chief, Engineer Support Lab.
Fort Devens, MA 01433		STRBE-N Chief, Engineer Service Support
President		Lab. STRBE-E
US Army Armor and Engineer Board		Chief, Logistics Support Lab. STRBE-G
ATTN: ATZK-AE-PD-E Fort Knox, KY 40121		Chief, Matl. Fuels & Lubricants Lab. STRBE-V
Commander & Director		Director, Product A&T Directorate, STRBE-T
USA FESA		CIRCULATE
	-	Mara Pal Pilii
Fort Belvoir, VA 22060	.)	Matls, Fuels, & Lub Lab, STRBE-V
Director	5	Fuel & Lub Div. STRBE-VF
US Army TRADOC Systems Analysis Activity	30	Hyd Fluid & Co - Prev Br. Sec/Grp. STRK3E-VFH
• •	3	Tech Reports Ofc, STRBE-WPG
White Sands Missile Range, NM 88002	3	Security Ofc (for liaison officers), STRBE-S
	2	Tech Library, STRBE-WC
HQ. USAEUR & Seventh	1	Program Support, STRBE-HR
Army Deputy Chief of	1	Public Affairs Ofc, STRBE-I
Staff Engineer	1	Ofe of Chief Counsel, STRBE-L
ATTN: AEAEN-MT-P		
APO New York 09403		Department of the Navy
HQ. USAEUR & Seventh Army	t	Director, Physics Program (421)
Operations		Office of Naval Research Arlington, VA 22217
APO New York, 09403	2	Commander, Naval Facilities
		Engineering Command
Belvoir R&D		Department of the Navy
Center		ATTN: Code 032-B. 062 200 Stovall St
Commander, STRBE-Z		Alexandria, VA 22332
Technical Director, STRBE-ZT		fig \$1 Las La Arm.
Assoc Technical Director. STRBE-11	1	US Naval Oceanographic Office Navy Library/NSTL Station
Chief Engineer, STRBE-HE		Bay St. Louis, MS 39522
Chief Scientist, STRBE-HS		
Program Planning, STRBE-HP		
Program Support. STRBE-HR		
Systems Analysis, STRBE-HA CIRCULATE	•	
	Commander IIQ. 39th Engineer Battalion (Cht) Fort Devens, MA 01433 President US Army Armor and Engineer Board ATTN: ATZK-AE-PD-E Fort Knox, KY 40121 Commander & Director USA FESA ATTN: FESA-TS Fort Belvoir, VA 22060 Director US Army TRADOC Systems Analysis Activity ATTN: ATAA-SL (Tech Lib) White Sands Missile Range, NM 88002 HQ. USAEUR & Seventh Army Deputy Chief of Staff Engineer ATTN: AEAEN-MT-P APO New York 09403 HQ. USAEUR & Seventh Army Deputy Chief of Staff, Operations ATTN: AEAGC-FMD APO New York, 09403 Belvoir R&D Center Commander, STRBE-Z Technical Director, STRBE-H Chief Engineer, STRBE-HE Chief Scientist, STRBE-HE Chief Scientist, STRBE-HB Program Planning, STRBE-HR Systems Analysis, STRBE-HR Systems Analysis, STRBE-HA	Commander IIQ. 30th Engineer Battalion (Cbt) Fort Devens. MA 01433 President US Army Armor and Engineer Board ATTN: ATZK-AE-PD-E Fort Knox. KY 40121 Commander & Director USA FESA ATTN: FESA-TS Fort Belvoir. VA 22060 Director US Army TRADIC Systems Analysis Activity ATTN: ATAA-SL (Tech Lib) White Sands Missile Range, NM 88002 HQ. USAEUR & Seventh Army Deputy Chief of Staff Engineer ATTN: AEAEN-MT-P APO New York 09403 HQ. USAEUR & Seventh Army Deputy Chief of Staff, Operations ATTN: AEAGC-FMD APO New York, 09403 Belvoir R&D Center Commander, STRBE-Z Technical Director, STRBE-IE Chief Engineer, STRBE-HE Chief Engineer, STRBE-HE Chief Engineer, STRBE-HE Chief Engineer, STRBE-HB Program Planning, STRBE-HR Systems Analysis, STRBE-HR Systems Analysis, STRBE-HR Systems Analysis, STRBE-HR

No. Copies	Addressee	No. Copies	Addressee
l	Library (Code L08A)		Others
	Civil Engineering Laboratory		
	Naval Construction Battalion	i	Professor Raymond R. Fox
	Center		School of Engineering and
	Port Hueneme, CA 93043		Applied Science George Washington University
1	Director		Washington, DC 20052
	Earth Physics Program		
	Code 464	1	Reliability Analysis Center
•	Office of Naval Research		Rome Air Development Center
	Arlington, VA 22217		RADC/RBRAC (I. L. Krulac) Griffiss AFB, NY 13441
ı	Naval Training Equipment		
	Center		
	ATTN: Technical Library		
	Orlando, FL 32813		
	Department of the Air Force		
1	HQ USAF/RDPT		
	ATTN: Mr. Allan Eaffy		
	Washington, DC 20330		
1	HQ USAF/LEEEU		
	Chief, Utilities Branch		
	Washington, DC 20330		
1	US Air Force		
	HQ Air Force Engineering &		
	Services Center		
	Technical Library FL 7050		
	Tyndall AFB, FL 32403		
ı	Chief, Lubrication Br		
	Fuels & Labrication Div		
	Wright-Patterson AFB.		
	OH 45433		
ı	Department of Transportation		
	Library, F0B 10A, M494-6		
	800 Independence Ave., SW		
	W: 1: . 124: 30001		

Washington, DC 20591

BULLIED)

8

MANNA (O)